

Actuator Fitment • Inertech


designed for use with

FSL Inert Clean Agent Gaseous Suppression Systems

See the Inertech manual for the installation procedure and sequence

IMPORTANT

Screw actuator down until firm and approximately 2 threads are showing



Using spanner (A/F 46mm) screw actuator down so that there are 2 threads showing on the cylinder valve connection

Use spanner NF34910

